

4055497; P100 fit test filter

- Individually Packaged
- Use for Fit Testing positive or negative pressure masks
- Simply screw into the end of fit test adapter
- Can perform hundreds of fit test

